Oil Field Environmental Incident Summary

Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC **Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: RUPPERT 1
Field Name: PORTAL
Well File #: 2362
Facility ID #: 102362
County: BURKE

Twp Rng Sec Qtr: 164 92 34 SW NW

Location Description:

Submitted By: Bill Bender

Received By:

Contact Info: Bill Bender

5005 LYNDON B JOHNSON FREEWAY

SUITE 700

DALLAS TX 75244

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 10233 Feet
Nearest Water Well: 10233 Feet

Type of Incident: Equipment Failure Release Contained: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 30 Barrels 29 Barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

No immediate explosive atmosphere or health hazard risk.

Areal Extent:

N/A

Potential Env. Impacts:

No impact to surface water or ground water.

Action Taken/Planned:

A vacuum truck recovered the free liquid. Affected soil inside the berm will be scraped-up, collected and disposed of at an approved disposal facility.

Wastes Disposal Location:

At an approved disposal facility.

Other Agencies Involved:

Updates

Date: 12/28/2020 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Lund, Dylan

Notes:

According to the incident report, the release was contained to the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update